




CAM (Surf Cam)

- Instructor - Robert Tosch Ext. 7421
- Course Objectives
 - Bolt circle on clock
 - work on parts for clock
 - Use CAM software to create a CNC program for a name plate
 - CNC name plate
- Lunch
 - Finish mill & drill clock
 - CNC mill/engrave face
 - Assemble clock



Bolt circles

- Bolt circles are common on flanged parts
 - **Trig** can be very useful in finding the hole locations




Type "A" bolt circles

- Note origin for dimensions
- Determine the X, Y value for hole #5 for a 9 hole pattern on a 5" bolt circle

– X =

– Y =



7 Holes		8 Holes		9 Holes	
x1	0.50000	x1	0.50000	x1	0.50000
y1	0.00000	y1	0.00000	y1	0.00000
x2	0.10908	x2	0.14645	x2	0.17861
y2	0.18826	y2	0.14645	y2	0.11698
x3	0.01254	x3	0.00000	x3	0.00760
y3	0.61126	y3	0.50000	y3	0.41318
x4	0.28306	x4	0.14645	x4	0.06699
y4	0.95048	y4	0.85355	y4	0.75000
x5	0.71694	x5	0.50000	x5	0.32899
y5	0.95048	y5	1.00000	y5	0.96985
x6	0.98746	x6	0.85355	x6	0.67101
y6	0.61126	y6	0.85355	y6	0.96985
x7	0.89092	x7	1.00000	x7	0.93301
y7	0.18826	y7	0.50000	y7	0.75000
		x8	0.85355	x8	0.99240
		y8	0.14645	y8	0.41318
				x9	0.82139
				y9	0.11698


Type "B" bolt circles

- Note origin for dimensions – central coordinates

– Determine the X, Y value for hole #7 for a 18 hole pattern on a 6" bolt circle

– X =



– Y =



17 Holes		18 Holes		19 Holes	
x1	-0.09187	x1	-0.08682	x1	-0.08230
y1	-0.49149	y1	-0.49240	y1	-0.49318
x2	-0.26322	x2	-0.25000	x2	-0.23797
y2	-0.42511	y2	-0.43301	y2	-0.43974
x3	-0.39901	x3	-0.38302	x3	-0.36786
y3	-0.30132	y3	-0.32139	y3	-0.33864
x4	-0.48091	x4	-0.46985	x4	-0.45789
y4	-0.13683	y4	-0.17101	y4	-0.20085
x5	-0.49787	x5	-0.50000	x5	-0.49829
y5	+0.04613	y5	0.00000	y5	-0.04129
x6	-0.44758	x6	-0.46985	x6	-0.48470
y6	+0.22287	y6	+0.17101	y6	+0.12274
x7	-0.33685	x7	-0.38302	x7	-0.41858
y7	+0.36950	y7	+0.32139	y7	+0.27347
x8	-0.18062	x8	-0.25000	x8	-0.30711
y8	+0.46624	y8	+0.43301	y8	+0.39457
x9	0.00000	x9	-0.08682	x9	-0.16235
y9	+0.50000	y9	+0.49240	y9	+0.47291
x10	+0.18062	x10	+0.08682	x10	0.00000
y10	+0.46624	y10	+0.49240	y10	+0.50000
x11	+0.33685	x11	+0.25000	x11	+0.16235
y11	+0.36950	y11	+0.43301	y11	+0.47291

Topaz bolt circle

- Read the manual
 - Bolt Hole Circle” mode
 - LED shows the letter “C” for center.
 - Press [>] to move to the next input.
 - Follow the LED directions



HASS Bolt Circle

EDIT: IPS JOG

```

MDI N00000000
(CIRCLE BOLT PATTERN) ;
;
(SPOT DRILL) ;
T1 M06 ;
G00 G90 G54 X0. Y0. ;
S7500 M03 ;
G43 H01 Z0.2 M08 ;
G83 G98 Z-0.125 F49.995 Q0.125 L1 ;
G70 I3. J0. L12 ;
G00 G80 Z0.2 M09 ;
M05 ;
G28 G91 Z0 ;
G00 G90 G54 X0 Y0 ;
M01 ;
;
(DRILL) ;
T2 M06 ;
G00 G90 G54 X0. Y0. ;
S7500 M03 ;
G43 H02 Z0.2 M08 ;
G83 G98 Z-0.75 F49.995 Q0.125 L1 ;
G70 I3. J0. L12 ;
G00 G80 Z0.2 M09 ;
M05 ;
G28 G91 Z0 ;
G00 G90 G54 X0 Y0 ;
M01 ;
    
```

MANUAL	SETUP	FACE	DRILL	POCKET MILLING	ENGRAVING	VQC		
CENTER DRILL 0	DRILL TOOL 0	TAP TOOL 0						
CENTER DEPTH 0.0000 in	DRILL DEPTH 0.0000 in	TAP DEPTH 0.0000 in						
CENTER PECK 0.0000 in	DRILL PECK 0.0000 in							
WRK ZERO OFST 54	R PLANE 0.2000 in	NUM OF HOLES 0						
X CENTER PT 0.0000 in	DISTANCE 0.0000 in							
Y CENTER PT 0.0000 in	START ANGLE 0.000 deg							
BOLT CIRCLE			BOLT LINE		SINGLE HOLE		MULTIPLE HOLES	

Press <CYCLE START> to run in MDI or <F4> to record output to a program.

Enter the center drill tool number.
Enter '0' to skip center drilling cycle.
Press **CANCEL** to exit current mode



MAIN SPINDLE

SPEED(RPM) 0

LOAD(%) 0%

SP LD: 0.0 KW
SURF SPD: 0 FPM
CHIP LOAD: 0.00000
FEED RATE: 0.
ACT FEED: 0.
GEAR: LOW

POSITION: (IN) JOG RATE 0.0010 LOAD

MACHINE

X	0.0000		0%
Y	0.0000		0%
Z	0.5863		0%


ACTIVE TOOL

T1

LOAD 0 LIFE 100%
SPOT DRILL

7 SPINDLE 100% FEED 100% RAPID 100%

Clock Face



CAM - SURFCAM

- Why is CAM valuable
 - As compared to manual programming
- CAD/CAM Boosts productivity
 - Speeds up CNC programming – by allowing the programmer to automatically generate the NC program from the engineering CAD data
 - Reduces machine set up time – reduces the program prove out time
 - Especially critical where lot sizes are small and/or parts are complex

Learning any CAM Software


- (6) processes for all CAM Systems
- Job Setup
 - Axis selection, Retract (safety) Plane, Stock, Work holding, Machine Specific equipment
- Geometry selection
 - Geometry to machine, offsets Geometry, containment boundaries
- Tool selection
 - Tool definition, flutes, material, chip load & cutting speed

Learning any CAM Software - Continued

- (6) processes for all CAM Systems
- Machining Strategy
 - Cut direction, tolerances, radial cut, axial cut, High Speed Machining options
- Speeds & Feeds
 - Approach feed, Machining Feed, Retract feed, slow down feed, Spindle Speeds
- Approach & Retract into & out of Cuts
- \$\$\$ Cycle time reduction

SURFCAM Screen layout

- Help screen
 - Contents
 - Store to T drive –
Backup to Thumb drive
- Save early & often
- Hot keys increase your productivity
 - Underline = hot key
 - Display the Tap / Drill Chart. Press CTRL+T





Layers & Colors

- Layers
 - Create geometry on different layers
- Color
 - Select color when creating geometry




Getting started

- Cartesian coordinate system
- Origin Point – X0Y0
- Create Geometry
 - Points
 - Lines
 - Circles
- Fillet & Chamfer
- Right & Left mouse buttons
 - Center roller



Screen icons

- New, Open & save
- Delete
- Transform
 - Copy
 - Move
- Operations manager




Point Geometry



- Selection options – determines how geometry is located
 - Sketch = danger not accurate
 - End point = end point of existing geometry
 - Center = select arc geometry to find center
 - Keyboard = Enter X, Y, and Z coordinates
 - Quadrant = select quadrant of circle


Line Geometry




- Selection options

- Tangent = tangent to an arc
- Horizontal = horizontal line
- Vertical = vertical line
- Angle = create line at an angle
- Offset = offset for a line (awesome feature)
- Rectangle = create a box

Circle Geometry




- Selection options
 - Center/Radius
 - Center/Diameter
 - Create > fillet = create fillet between geometry
- Create geometry using keyboard entry & existing geometry



Keyboard Input

- Create line
 - End points > keyboard
- 6.00 x -2.00 dimensions
 - create a box



A screenshot of a software dialog box titled "Construction View". It features three input fields for coordinates: "X value" with "0.00000", "Y value" with "0.00000", and "Z value" with "0.00000". To the right of these fields are two buttons: "OK" and "Cancel".


X0,Y0

2.00"

6.00"

Edit color & Change layers

- Create Dimensions
 - Leader dimensions




X0,Y0

2.00"


6.00"

Edit > Trim/Break

- Trimming One Entity
 - digitize entity to keep (area to keep)
 - digitize the trim too entity




- Trimming Two Entities
- Radius trim
- Breaking an Entity
 - digitize the first entity
 - digitize the entity to break too.
- Be aware of where you select the element




Create box

- Create a 2 x 6 rectangle
- Save file to thumb drive




Create text

- Font type: True type
- Font: Stencil
- Text height size to fit 2 x 6 rectangle





Explode text

- Edit Text & explode




Add cutter path

- Load cutter & change to tool #1
- Change feed rates to 10.0
- Change cutting method to on geometry
- Select geometry, depth .010 & press OK




Generate CNC code

- Open operations manager
- Select post icon




Select Post & generate code

- Select machine: Haas VF series
- Verify F words (feed to 10.)
- Save code to thumb drive



```
litNC - [name plateAAA.NCC]
le Edit Search Action Calcs Analysis DNC Window Help
1 O0
- (MACHINE: HAAS VF-SERIES MPost Library)
- G17 G40 G80 G90
5 T1 M6
- S10417 M3
- G0 G90 G1 X1.0036 Y-1.4999
- G43 Z1. H1 M8
- (ENGRAVE )
10 Z0.1
- G1 Z-0.0044 F1.042
- X1.3541 Y-1.4997 F2.083
- X1.3678 Y-1.4986
- X1.3783 Y-1.4967
15 X1.3863 Y-1.4941
- X1.3916 Y-1.4913
```



Clock Face bolt circle



Assignment

- Split in 2 groups
 - Continue milling/drilling for clock
 - Assemble clock
 - CNC mill name plate

- 1) Create part outline & add text
text will be of suitable size to fit material
- 2) Explode text & add cutter path
- 3) Generate CNC code & save to thumb drive
- 4) Load program in CNC machine, Zero tool
- 5) CNC Engrave Name plate



Engrave name .01 deep

ACC Grant Information

“Powerpoint2” by Bob Tosch, Building Career Pathways in the STEM Cluster: Closing the Skill Gaps in Northeast Michigan, Alpena Community College is licensed under CC BY 4.0. To view a copy of this license, visit <https://creativecommons.org/licenses/by/4.0/>.

ACC is sponsored by a \$2.5 million grant from the U.S. Department of Labor, Employment & Training Administration TAACCCT Grant #TC-26458-14-60-A-26. It is the policy of Alpena Community College (ACC) to comply with Section 504 of the Rehabilitation Act of 1973, as amended, and with the Americans with Disabilities Act of 1990 (ADA). These acts provide for equal opportunity for students with disabilities in educational activities, programs, and facilities. ACC is committed to affording equal opportunity to persons with disabilities by providing access to its programs, activities, and services.

This workforce product was funded by a grant awarded by the U.S. Department of Labor’s Employment and Training Administration. The product was created by the grantee and does not necessarily reflect the official position of the U.S. Department of Labor. The U.S. Department of Labor makes no guarantees, warranties, or assurances of any kind, express or implied, with respect to such information, including any information on linked sites and including but not limited to, accuracy of the information or its completeness, timeliness, usefulness, adequacy, continued availability, or ownership.

