1. Running the Simulation:

- Verify selected operations
- Observe the process; does it make sense?
- Modify tool paths as needed
- Final run
- Generate G-cone

MAC 240 CAD/CAM 2D